

Shop Name: BK Consulting

Tel: 731-632-1722

Email: bkreft@hotmail.com

Address: 5051 Highway 22 North
Adamsville, TN, Adamsville, 38310 1726, TN

Technician

Date&Time:

2019-07-09 14:00:22

Customer
information

Title 2003 GM (T) GMC Truck

Year 2003

VIN: 2GTEC19T331280635

Make GM

Lic Plate

Model (T) GMC Truck

Odometer
MileageSub model FULL SIZE TRUCK 4x2, 1500 (1/2
TON),(9) EXTENDED CAB/EXTENDED
VAN

Color

Engine

Status

Status

Technician notes

Scan report

System	Status
Powertrain	Fault 5
Anti-lock brake system	Pass No Fault
Supplemental inflatable restraint	Pass No Fault
Body control module	Pass No Fault
Instrument panel cluster	Pass No Fault
Driver door module	Pass No Fault
Driver seat module	Fault 2
Heating and air conditioning	Fault 1
Passenger door module	Pass No Fault
Radio	Pass No Fault
OnStar	Pass No Fault
Passenger presence system	Pass No Fault
Diagnostic circuit check	Pass No Fault

DTC

System	Codes	Description	Status
Powertrain	P0101	Mass Air Flow (MAF) sensor performance	Current DTC Last test: Not ran This ignition: Not ran Since cleared:Passed & failed History

Powertrain	P0102	Mass Air Flow (MAF) sensor circuit low frequency	Current DTC Last test: Not ran This ignition: Not ran Since cleared:Passed & failed History
Powertrain	P0171	Fuel trim system lean bank 1	Current DTC Last test: Failed This ignition: Not ran MIL requested Since cleared:Passed & failed History
Powertrain	P0174	Fuel trim system lean bank 2	Current DTC Last test: Failed This ignition: Not ran Since cleared:Passed & failed
Powertrain	P1514	Throttle body performance	Current DTC Last test: Not ran This ignition: Not ran Since cleared:Passed & failed History
Driver seat module	B1960	Seat side bolster sensor circuit	History DTC
Driver seat module	B2355	Front vertical sensor malfunction	History DTC
Heating and air conditioning	B3770	Air flow control 6 feedback circuit	History DTC