

Full Diagnostic Report

The Report is created by **THINKCAR**

Repair Shop

Shop Name:b

Address:

Telephone:

Email:bethany5436@gmail.co

SN:960640005210

Test Time:08/07/2023 12:37:25

Vehicle Information

Year:2013

Vehicle brand:Ford

Model:Mustang

VIN:1ZVBP8JZ8D5271314

Odometer:31418miles

Vehicle Software Version:V10.42



Inspection Result

IPC (Instrument Panel Control Module) 1 problems exist

1.U0401:81-0A Data Received From ECM(Engine Control Module)/PCM (Powertrain Control Module) A Is Invalid

PCM (Powertrain Control Module) 2 problems exist

1.P0300:00-EC Detected Random Misfire

2.P0316:00-6C Misfire Detected On Startup (First 1000 Revolutions)

The following systems are OK:

1.ABS (Anti-Lock Braking System)

2.ACM (Audio Control Module)

3.APIM (Accessory Protocol Interface Module)

4.BCM-B (Body Control Module B)

5.FCIM (Front Controls Interface Module)

6.GEM/SJB (Generic Electronic Module/Smart Junction Box)

7.HVAC (Heating Ventilation Air Conditioning)

8.OCSM (Occupant Classification System Module)

9.PSCM (Power Steering Control Module)

10.RCM (Restraint Control Module)

11.VDM (Vehicle Dynamics Module)