

Full Diagnostic Report

The Report is created by **THINKCAR**

Repair Shop

Shop Name:b

Address:

Telephone:

Email:bethany5436@gmail.co

SN:960640005210

Test Time:08/07/2023 08:20:17

Vehicle Information

Year:2013

Vehicle brand:Ford

Model:MUSTANG

VIN:1ZVBP8JZ8D5271314

Odometer:31418 miles

Vehicle Software Version:V10.42



Inspection Result

PCM (Powertrain Control Module) 2 problems exist

1.P0300:00-AF Detected Random Misfire

2.P0316:00-6C Misfire Detected On Startup (First 1000 Revolutions)

The following systems are OK:

1.ABS (Anti-Lock Braking System)

2.ACM (Audio Control Module)

3.APIM (Accessory Protocol Interface Module)

4.BCM-B (Body Control Module B)

5.FCIM (Front Controls Interface Module)

6.GEM/SJB (Generic Electronic Module/Smart Junction Box)

7.HVAC (Heating Ventilation Air Conditioning)

8.IPC (Instrument Panel Control Module)

9.OCSM (Occupant Classification System Module)

10.PSCM (Power Steering Control Module)

11.RCM (Restraint Control Module)

12.VDM (Vehicle Dynamics Module)