

2009 Dodge or Ram Truck Journey FWD V6-3.5L

Vehicle > ALL Diagnostic Trouble Codes (DTC) > Testing and Inspection > P Code Charts

Possible Causes
EXCESSIVE RESISTANCE IN THE (F856) 5 VOLT SUPPLY CIRCUIT
EXCESSIVE RESISTANCE IN THE (K34) EGR SIGNAL CIRCUIT
EXCESSIVE RESISTANCE IN THE (K900) SENSOR GROUND CIRCUIT
EXCESSIVE RESISTANCE IN THE (Z901) GROUND CIRCUIT
EXCESSIVE RESISTANCE IN THE (K35) EGR CONTROL CIRCUIT
(K34) EGR SIGNAL CIRCUIT SHORTED TO GROUND
EXHAUST GAS RECIRCULATION VALVE