

Vehicle diagnostic report



Shop Name:
Address:
Telephone:
Email :
Fax:



Diagnostic Result

Fault (2)

ABS (Anti-lock Braking System)	(4)	Abnormal
--------------------------------	-------	----------

C2206 Vehicle Configuration Mismatch	Active
C2202 Original VIN Mismatch/Missing	Active
U0100 Lost Communication With ECM/PCM	Active
U0141 Lost Communication With IPM (FCM/TIPM)	Active

BCM (Body Control Module/TIPMCGW/FCMCGW)	(1)	Abnormal
--	-------	----------

U0100 Lost Communication With ECM/PCM	Active
---------------------------------------	--------

Normal (9)

PCM (Powertrain Control Module)	Normal
TCM (Transmission Control Module)	Normal

SRS (Supplemental Inflatable Restraint System/ORC)	Normal
CCN (Cabin Compartment Node/Instrument Cluster)	Normal
WCM (Wireless Control Module)	Normal
HVAC (Heating Ventilation Air-conditioning and Cooling)/AC (Air Conditioning)	Normal
RADIO	Normal
EOM (Electronic Overhead Module)	Normal
SDAR (Satellite Digital Radio)	Normal