




5/8/2019 4:11:00 PM

	1	2	Δ	1/ Δ
Time Axis	-279.4 ms	-272.9 ms	6.534 ms	153 Hz
Channel A	-1.152 V	--	--	
Channel B	-495.6 mV	--	--	

Vehicle

CHA A = INLET CAMSHAFT ACTUATOR SIGNAL
= EXHAUST ACTUATOR GROUND

CHA B = EXHAUST CAMSHAFT ACTUATOR SIGNAL

CHA C = INLET ACTUATOR GROUND

CHA D